

(Model 8170-9001 replaces 8170 and 8170F)

#### **DESIGN FEATURES**

Body: Bronze
Impeller: Neoprene
Shaft: Stainless Steel
Bearings: Ball Bearing
Ports: 3/4" I.P.T.

### SERVICE KITS

MINOR SERVICE KIT—For "onboard" repairs—includes impeller, seal and gasket.

MAJOR SERVICE KIT—For major pump overhaul includes all parts except body.


APPLICATION: Marine engine cooling for Chrysler marine engines series M-46-4, M-47-4.

### OPERATING INSTRUCTIONS

- INSTALLATION—Care should be taken that the intake and discharge piping of the engine corresponds with the port as shown on the installation drawing.
- 2. DRIVE-Direct.
- SPEEDS—Pump is designed to operate through the entire engine range.
- SELF-PRIMING—Jabsco Pumps will operate satisfactorily at low as well as high speeds. Be sure suction lines are airtight.
- RUNNING DRY-Impeller depends on liquid pumped for lubrication. DO NOT RUN DRY for more than 30 seconds. Lack of liquid will burn the impeller.
- PRESSURES—Excessive back pressure due to scale and rust deposits in the water passages will reduce the flow and cause engine to overheat.
- TEMPERATURES—Impeller specially compounded to operate through the range of 45° - 180° F. For temperatures of 27° - 45° F. use -09 impeller.

- FREEZING WEATHER—Drain unit by loosening end cover plate. For closed systems, use one of the following anti-freeze compounds: Atlas "Permaguard", DuPont "Zerex", Dow Chemical "Dowguard", "Pyro", or "Telar". Do not use petroleum based anti-freeze compounds.
- IMPELLER REPLACEMENT—Remove end cover. Withdraw impeller by grasping impeller hub with pliers.
- GASKET REPLACEMENT—Always use standard pump part. A thicker gasket will reduce priming ability. A thinner gasket will cause impeller binding.
- CAM REPLACEMENT—Coat top surface of new cam and cam screw threads with permatex #1 or equivalent sealing compound before installing.
- SPARE PARTS—Avoid costly shut downs by always having a JABSCO Service Kit on hand.

# JABSCO PRODUCTS III



### PARTS LIST


KEY	PART NO.	QTY. REQ'D.	DESCRIPTION
1	91003-0010	6	End Cover Screw
2	8175-0010	1	End Cover
3	3101-0000	1	*Gasket
4	920-0001	1	*Impeller
5	4156-0000	- 1	Wearplate
6	96080-0080	1	*Seal
7	91004-0110	1	Cam Screw
8	3255-0000	1	Cam
9	8174-9000	1	Body
10	8177-0410	1	Shaft
11	91402-0060	1	Key
12	913-0000	1	Bearing Seal
13	92600-0060	1	Ball Bearing
14	91701-1850	1	Retaining Ring
15	8176-0000	1	Coupling
16	91700-2470	1	Retaining Ring

90118-0001 Service Kit contains parts marked with asterisk.

Model 81-70 Lip Seal Version (obsolete)

92700-0060 - Seal 92000-0210 - 'O' Ring 3166 - Spacer 3298 - Slinger

Face seal cannot be installed in lip seal version.



## JABSCO PRODUCTS ITI

Marine and Recreation Components Division International Telephone and Telegraph Corporation 1485 Dale Way, Costa Mesa, California 92626

Telephone: (714) 545-8251